

HUBBARD COMMUNICATIONS OFFICE
Saint Hill Manor, East Grinstead, Sussex.

Dir. Mat of
All Cen. Orgs.
HCO Secs.
Fowler and Allen.

HCO POLICY LETTER OF JANUARY 30, 1961

BRITISH E-METER BREAKAGE

It has been found by our electronics repair man in Johannesburg that the transistors in the British Model E-Meter are cracking or disconnecting on some cases during shipment after being checked out okay at Saint Hill.

If British Meters fail in your area on arrival this should be looked into at once.

Please report to me the costs you have laid out in repairing transistors on these meters.

L. RON HUBBARD.

LRH:aec:js
Copyright (c) 1961
by L. Ron Hubbard.
ALL RIGHTS RESERVED.